





Содержание



POE	3
-----------	---




POE

IEEE802.3af



RT9400		link	237p.	15W (5V, 12V, 24V)	
RT9460		link	237p.	15W (3.3V)	


DP9200		link	330p. 13W (5V)	56x14mm
DP1435		link	346p. 13W (5V)	35.6x14mm
DP9900M-		link	396p. 13W (5V)	21.2x14x13.35mm

RT7640		link 678p.	30W (5V)	
PD13C01		link 687p.	10W (5V, 12V)	51x14x12mm
38x38 1		link 159p.	12W (12V)	38x38x?mm

38x38 2		link	167p. 13W (12V)	38x38x?mm
38x38 3		link	212p. 15W/24W? (12V)	38x38x?mm
38x38 SD4932B		link	188p. 12W (12V)	38x38x?mm

PM3812R		link	216p. 12W (12V)	38x38x?mm
----------------	--	-------------	------------------------	------------------





PIN ASSIGNMENT

Pin #	Name	Description
1	VA1	RX Input (1). This input pin is used in conjunction with VA2 and connects to the centre tap of the transformer connected to pins 1 & 2 of the RJ45 connector (RX) - it is not polarity sensitive.
2	VA2	TX Input (2). This input pin is used in conjunction with VA1 and connects to the centre tap of the transformer connected to pins 3 & 6 of the RJ45 connector (TX) - it is not polarity sensitive.
3	VB1	Direct Input (1). This input pin is used in conjunction with VB2 and connects to pin 4 & 5 of the RJ45 connector - it is not polarity sensitive.
4	VB2	Direct Input (2). This input pin is used in conjunction with VB1 and connects to pin 7 & 8 of the RJ45 connector - it is not polarity sensitive.
5	GND	DC Return. This pin is the return path for the +VDC output.
6	VOUT	DC Output. This pin provides the regulated output from the DC/DC converter.

Package